

Installation Instructions: Windows Driver for SPORTident Red Thermal Printer



1. Extract all the files in the zip to a temporary folder.
2. Execute **SPORTidentPrinterInstall&Test.exe** and choose the **Run** option.
3. Select **POS-58 Series Printer**
4. Attach printer to computer using USB lead and switch on printer
5. Wait until the printer is recognised by the computer and the installation of the USB port is complete. This may take some seconds on Windows 7/8 computers
6. Then click **USB Port Check**. Within a few seconds the USB Port number should appear in the **Ports** field and the USB port number should print on the printer
7. Decide if the printer will be your default Windows printer (unlikely) and untick the **set as default printer** box. You can also untick **Create Shortcuts**
8. Click **Begin Setup** and when you see the message **Windows can't verify the publisher of this driver software**, choose the option **Install this driver software anyway**. Please be patient until the setup completes
9. When the setup is complete a **Windows POS-58 Properties** screen will appear. Click **Print Test Page**
10. If a Windows test page prints, the printer setup is complete
11. If nothing prints, Windows has applied the incorrect port to the printer. In this case, click the **Ports** tab and you may see that **LPT1** is ticked. This is incorrect and so scroll down and tick the USB port that was allocated earlier in the install process. Click **Apply** and the Windows test page should print successfully
12. All Done!